

DANFOSS EXTENDED WARRANTY

For a period of ten (10) years from the date of purchase Danfoss warrants that the Danfoss GX cable is free from defects in material, design and workmanship. The extended warranty is only valid if the resistance table on page XX and the warranty certificate on page XX are correctly filled out and the installation is in accordance with the installation instructions.

The filled out resistance table and the warranty certificate shall be presented to Danfoss in the case a claim is made. The defective Danfoss GX has to be inspected by or submitted to Danfoss or an authorized Danfoss GX dealer. Failure to comply with all of the foregoing will void this extended warranty.

Danfoss will, when the customer has documented that a defect in the Danfoss GX was present at the date of delivery, repair or supply a new Danfoss GX at Danfoss' option. All claims shall be made within the extended warranty period. Danfoss shall not be liable for any claims made later than ten years from date of purchase. Danfoss shall not be liable for any consequential and secondary costs or damages linked to the defect or replacement of the Danfoss GX.

Danfoss will be liable for any costs related to the dismantling of defective product and the installation of a new product; however, such liability is limited to the amount of five (5) times the invoice value of the initial product supplied for each Damage/case.

THE FOREGOING WARRANTY IS EXPRESSLY IN LIEU OF ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, ON THE PART OF DANFOSS. DANFOSS DISCLAIMS ANY WARRANTY, EXPRESS OR IMPLIED, OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. DANFOSS NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON, FIRM OR CORPORATION TO ASSUME FOR IT ANY OTHER LIABILITY IN CONNECTION WITH SALE OR PRODUCT. DANFOSS SHALL NOT BE HELD RESPONSIBLE FOR DAMAGE TO PERSON OR PROPERTY, CONSEQUENTIAL LOSS, LOSS OF PROFIT, LOSSES ON GOODS IN STORE, OR THE LIKE WHICH MIGHT ARISE OUT OF THE FAILURE OF THE EQUIPMENT DELIVERED, IRRESPECTIVE OF THE CAUSE (INCLUDING FAULTY MANUFACTURE).